· .	\cup			\cup				
Missouri Department of Health & Senior Services Bureau of Environmental Health Services Lodging Establishment Inspection Report				FOR CENTRAL OFFICE USE ONLY		ESTABLISHMENT NUMBER		
Establishment Name Holiday Inn Express & Suites				Name X Alex Patel		eneral Manager		
Physical Address 2020 Jefferson Street				ə, MO	2ip 63775			
Mailing Address 2020 Jefferson Street			Perryvill	le, MO 63775				
County This inspection is a(n) 157 Initial Annual	Follow-up (573) 605			No of Rooms	ĭ Yes □	nt lodging license displayed? No INA- new		
Rooms Inspected: 105, 202, 204, 222, 303, 305, 317, 319	, 415, 417, 421					E Public		
	Swimming Po	e taken Yes INo Regulated by: DHSS IDNR cols/Spas (check all that apply)						
Please check if the following	New Lodging Estab	Indoor pool 🗵		pool Spa	Pool la	rger than 2000 square feet 🔲		
Iocal ordinances apply	Smoke detectors hardw			N/A Swimming	Pool Certified	Yes No N/A		
 Plumbing Swimming Pools/Spas 	Fire alarm system insta			4		The second secon		
Fuel Burning Appliances	Sprinkler system install			N/A Historical E	-	Yes X No N/A		
Based on an inspection this day, the ite renewal of your lodging license. Failure and/or prosecution. Owners may reque	to comply with any time	limits for correcti	ons specified i	in this notice may	result in revoca	ation of your lodging license		
(RSMo 315.005-065, 19 CSR 20-3.050	t=Not In Compliance, e			NO=Not O		VA=Not Applicable		
Section A & B: Water Supply & Was 1. Approved source, construction and o	ewater in Out	NO NA S	ection E: Fir					
2. Complies with water quality standard 3. Chlorinator maintained and operated	s 🗵 🗖		. Fire extinguis	sher type, inspect lings fire-rated, so	ed, and location			
4. Wastewater operation and maintenar Section C: Sanitation/Housekeeping	nce X	4	. Doors, self-c	losing and fire-ral tors hardwired, ir	led			
1. Walls, floors and ceilings in good rep 2. Housekeeping practices and furnishing	air X 198 X	6	. Evacuation r	oute and plan, ins mps, maintained,	stalled, available			
3. Towels and bed linens clean 4. Mattresses and box springs clean	×		. Means of eg . Handrails an	ress, number, ma d balconies main	intained tained and appr	opriate		
5. Pest control procedures X Section F: Swimming Pools/Spas 6. Ice machines, scoops, liners clean & protected X Section F: Swimming Pools/Spas								
7. Garbage storage and disposal				Boundary line, pool depth properly marked				
Food Inspection conducted accordin 9. Food, equipment and single service/	g to 19CSR20-1.025	4	. Lifesaving	equipment adeq	uate, good re			
10 Each projected from contamination								
12. Handwashing facilities/hygienic practices				Electrical outlets, proper protection & distance				
1. Combustible/toxic items usage and s 2. Building maintained to assure safe co	torage ×		0. First ald kit					
3. CO detectors hardwired, Installed, go 4. GFCI, outlets & switches installed, go	od repair		ection G: Pl	umbing/Mechani dequate, good re	cal			
5. Exit signs installed, good repair 6. Emergency lighting installed, good re	X	2	. Ventilation a	dequate, plumbin valves adequate.	g, restrooms			
7. Electric panel protected, labeled, goo Required Annual Third Party Inspect	od repair 📃 💌	4	. Relief valve	discharge pipes in gaps, no cross c	nstalled, adequa	ate x		
1. Fire Alarm System 2. Sprinkler System	X	S S	ection H: Ho	el-burning appliar				
3. Local Fire and Building Codes/Ordin 4. Current Boiler/Pressure Vessels MD	PS		. Fire resistan	t room or sprinkle	er head			
Certification 5. Backflow Device(s) Test				eating/cooling un f appliances and				
6. Liquid Propane Leak Test INSPECTED BY (PRINT NAME ar		× 5	i. Operation an NUMBER A	d condition adeq	uate	TELEPHONE		
Melanie Zernicke	inf F.L	1682				573-547-6564		
LICENSING YEAR 2020 / 20 <u>21</u> A				ATE INSPECT	EU	FOLLOW UP DATE 08/04/2020		
RECEIVED BY (PRINT NAME AN						PAGE 1 OF 2		
Alex Patel P01564	Distribution White	Owner Canani	Central Office	Pink/Local Office	· - · ·	E9.02		
MA 200-0005 (0+ 10)	Distriction. Attrice	Condity:						

. . .

Time In: 9:45 am Time Out: 2:05 pm

		Page					
MISSOURI DEPARTMENT OF H BUREAU OF ENVIRONMENTAL LODGING ESTABLISHMENT IN	2 of 2						
Establishment Name: Holiday Inn Express & Suites	Physical Address: 2020 Jefferson Street	Perryvi	Perryville, MO				
SECTION REFERENCE	OBSERVATIONS AND ADDITIONAL	COMMENTS					
Swimming pool: F. 4: A Taylor test kit is used by inspector to verify chemical concentrations in saltwater swimming pool. Inspector reviewed daily operating records and discussed water testing frequency. The temperature of the swimming pool is 88.0°F with a pH of 8.4, and no free chlorine residual. Owner voluntarily closed pool by locking door and posting sign. Inspector will schedule a follow-up inspection to ensure that the swimming pool has a pH ranging from 7.2 to 7.8 and a free chlorine residual of at least 1 part per million (ppm) before pool is re-opened. F. 5: Railing on steps entering into saltwater swimming pool is loose. Ensure railing is tight and in good repair.							
Room 105 (Audio/Visual room): C. 3: Pillow case linens were observed with yellow-like staining. Clean linens shall be provided in the guest room each day that guest room is occupied by a different guest.							
Room 202: C. 3: Pillow case linens were observed with yellow-like staining. Clean linens shall be provided in the guest room each day that guest room is occupied by a different guest.							
Room 204: C. 3: Pillow case linens were observed with yellow-like staining. Clean linens shall be provided in the guest room each day that guest room is occupied by a different guest.							
Room 222: C. 3: Pillow case linens were observed with yellow-like staining. Clean linens shall be provided in the guest room each day that guest room is occupied by a different guest.							
Maintenance room on second floor: C. 1: Base board trim is torn away from wall and is in need of repair. Walls, floors, and ceilings of facility shall be kept clean and in good repair.							
Room 317: C. 3: Pillow case linens were observed with yellow-like staining; comforter also had a black stain. Clean linens shall be provided in the guest room each day that guest room is occupied by a different guest.							
Room 319: Comment: Discussed drawing on ceiling above shower in bathroom.							
Maintenance room on third level: D. 7: Circuit panels was observed not properly labeled. Access to electrical panels shall be unobstructed; fuses and circuits must be labeled for identification.							
Room 415: C. 3: Fitted bed sheet is observed with yellow-like staining. Clean linens shall be provided in the guest room each day that guest room is occupied by a different guest.							
Room 417: C. 3: Pillow case linens were observed with yellow-like staining. Clean linens shall be provided in the guest room each day that guest room is occupied by a different guest.							
Room 421: C. 3: Pillow case linens were observed with yellow-like staining. Clean linens shall be provided in the guest room each day that guest room is occupied by a different guest. H. 5: Filter on air conditioner is soiled with dust like debris. Air conditioning, heating, ventilating ductwork and related equipment shall be installed using acceptable procedures in a safe manner and be in good operating condition.							
Maintenance room on forth level: D. 7: Circuit panels was observed not properly labeled. Access to electrical panels shall be unobstructed; fuses and circuits must be labeled for identification.							
General: C. 2: Ice buckets in hotel rooms are not properly washed, rinsed and sanitized with a food-approved sanitizer as needed. If a food-grade single service liner is provided, the individual ice bucket/containers shall be washed rinsed and sanitized as needed. Reuse of the food-grade single service liner is forbidden.							
Comments: Discussed keeping laundry chute doors closed when not in operation. A copy of the inspection report will be email to alexpatel1480@gmail.com and a follow-up inspection will be conducted on 08/04/2020.							
Received by:	Melanie Zernicke	Date: 07/27/202	20				
Received by:	Alex Patel	Date: 07/27/202	20				

MO 580-0883 (1-09)